

RECEIVED
JAN 18 1991

DIVISION OF
OIL, GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) Jan. 1990 To (mo./yr.) Dec. 1990
2. DOGM File Number (original notice): M / 027/ 006
3. Mine Name: Cricket Mountain Lime Plant
4. Legal Description (Location of Lands Affected):
SW 1/4, SE 1/4, Section 25, Township 21S, Range R10W
SE 1/4, SW 1/4, Section 25, Township 21S, Range R10W
1/4, NE 1/4, Section 36, Township 21S, Range R10W
NW 1/4 Section 36 21S R10W
5. Mineral(s) Mined: Limestone
6. Name of Operator or Company: Continental Lime Inc.
7. Permanent Address: P.O. Box 266
Delta, Utah
84624

8. Company Representative (or designated operator):

Name: Russell Dobson
Title: Plant Manager
Address: P.O. Box 942 Delta, Ut. 84624
Phone: 864-4933

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 956,135 Tons

3. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected.

Developed 3 - 20 ft. high benches. Quarried 956,135 tons of
limestone and stripped 56,000 tons of Dolomitic limestone waste,
disturbing 4.6 acres.

4. Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.

We reclaimed 2 catch benches totaling less than 1 acre. Bench
was scarified, covered with 1 foot of - 1/2 limestone rejects,
re-vegetated and covered with a straw mulch. Results will be
evaluated this spring.

5. What was the total unreclaimed acreage at years end? 80 acres, more or less.

6. Briefly summarize mining and reclamation planned for the upcoming year.

We will mine two new benches to recover 1.2 million tons of
limestone, disturbing about 5 acres. We will not reclaim any old
disturbances because they are being used in on-going mining.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Russell Dobson

Title of Operator: Plant Manager

Signature of Operator: 

Date: Jan. 16, 1991

jb
MNMR-AR